

附件 6:

汽车主要维修设备一览表

序号	设备名称	型号	产地	数量	性能状况	购买时间
1	升降器	PRO-9D	上海	7	良好	2019.9
2	烤漆房	LH	绍兴	2	良好	2015.6
3	大梁校仪	CRE-B	烟台	1	良好	2015.8
4	台钻	Z50	永康	1	良好	2010.3
5	废机油回收机	3198	湖北	3	良好	2017.6
6	汽车冷媒加注回收设备	ZKB-3.6L	湖北	2	良好	2019.8
7	电脑检测仪	X-431	深圳	1	良好	2022.6
8	刹车碟光盘机	AM-983	德国	1	良好	2018.9
9	内径量表	50-160mm	上海	1	良好	2017.4
10	后刹车片更换专用工具		上海	1	良好	2022.6
11	汽车外形修复机	YING4500	山东	1	良好	2019.3
12	三元催化清洗机及尾气检测设备	行泰	宁波	1	良好	2021.6

备注:

1. 上述设备须附图说明;
2. 表格如不够, 可按同样格式扩展。

供应商名称(公章): 绍兴县壶镇镇伟青汽车修理厂

日期: 2026年1月4日



设备图片

大梁校正仪



四柱举升机






二柱举升机



四轮定位仪





电脑诊断议
4
3
1

轮胎充氮机




轮胎充气机



小剪举升机



气体保护焊



通用电脑监测仪



废机油回收机



钣金修复机



变速箱换油机



更换刹车片专用工具



烤漆房



内径表



汽车冷媒加注回收设备



汽车外形修复机



三元催化清洗机



刹
车
碟
光
机



台
钻



洗车机

