

附件 6:

汽车主要维修设备一览表

序号	设备名称	型号	产地	数量	性能状况	购买时间
1	汽车举升机	A1L-YD2-40	中国	4 台	良好	2013 年
2	气焊设备		中国	1 套	良好	2018 年
3	空气压缩机		中国	1 台	良好	2016 年
4	气体压缩机	NBC270S2	中国	1 套	良好	2019 年
5	发动机检测诊断仪	X. 431PR03S +V1. 0	中国	1 套	良好	2019 年
6	喷烤漆房及设备		中国	1 套	良好	2015 年
7	换油设备		中国	1 套	良好	2016 年
8	气缸压机表		中国	1 套	良好	2018 年
9	汽车专用万用表		中国	1 套	良好	2015 年
10	充电机		中国	1 套	良好	2018 年
11	发动机吊机		中国	1 台	良好	2015 年
.....						
N						

备注:

1. 上述设备须附图说明;
2. 表格如不够, 可按同样格式扩展。

供应商名称(公章): 缙云县长红机动车维修有限公司 日期: 2026 年 4 月 13 日







电瓶检测仪













































